







Fig. 2

1	Autociave	min	5	0	5	0	5	0	5	0	0	5	5	0	5	0	1	5	0	0	0		35<	
Steam Hood		min	0	5	1	1	0	5	0	5	5	10	0	5	0	. 5	0	0	5	10	0		/ 13	
Acid	regulator	g/l	2	2	2	2	2	2	2	2	7	2	2	. 2	2	2	2	2	2	2	2			
Wetting	Agent	g/l	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9	9			
i	Thickener		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
Dye	Concentrate	g/l	2	5	5	5	10	10	20	20	20	20	10	· 10	20	20	20	20	20	20	70			
-Ung	Target	шш	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150		i	FIG. S
	Overlap	%	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	95	20	20	20		30	
ırs	Robot speed	nm/sec	009	009	009	009	009	009	009	009	009	009	009	009	009	009	009	009	009	009	009			
Application Parameters	Fan Air Atom Air Fluid flow rate	cc/min	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	800	800	800	800	009	009	009	009	009			
Appli	Atom Air	Bar	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2			
	Fan Air	Bar	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5			
	, 4 7 F	lest No.	1	2	3	4	5	9	7	80	6	10	11	12	13	14	15	91	11	18	19			